

ACCESSORIES: PLUS POINTS FOR YOUR SII

Cylindrical and taper-shank end mills, shell end mills



Side mills, T-slot cutters, single and double angle cutters



Die sinking cutters, radius cutters



Cylindrical reamers up to approx. 200 mm (8") length



Countersinks, taps



Twist drills *)



Straight-fluted multi-step counterbores



Spiral-fluted multi-step counterbores



Form turning tools







Radius turning tools



Hollow-out turning tools, form cutters (radial relief, profile relief)



Universal index head 2555201	Support arm assembly 2576000	Roller arm 2589204	Spiral and relief grinding attachment 2580000
			
▲	▲		
▲			
▲	▲		
▲		▲	
▲	▲	▲ b)	
▲		▲ b)	
▲	▲	▲ b)	
▲			
▲	▲		▲
			

Notes on the accessory items

- a) Not required if only bevel lead/chamfer is ground.
- b) Required if tools are ground between centers or with end supported by center.
- c) Required if radius is generated with the aid of profiled grinding wheels.
- *) Special cup grinding wheels are required for the arc-shaped point.

